

Applicants: Rutten et al.  
Serial No.: 09/934,189  
Page 19

AMENDMENTS TO THE DRAWINGS

The attached replacement sheet includes changes to FIG. 3. This sheet, which includes changes to re-number inadvertently mislabeled reference numeral "56", indicating a distal attachment point for attaching the pull wire 50 at the distal segment 20, as described at page 13, lines 17-21, for example, to reference numeral "58". No new matter has been added.

3/6




FIG. 3